


# CPJTB EMERGENCY EXIT DOORS

## DOOR HARDWARE SCHEDULE

TCC is wanting to replace 3 doors and frames, each with **new hardware** that matches the manufacturer that have previously been spec'ed for the building, if possible. These are the exterior exit doors from the buildings 3 stairwells at the 1<sup>st</sup> floor level. The east and west doors are set up with electric strikes to provide badge access from the outside. The north door is not powered. (Electric strike not required at this opening.)



DOOR FRAME 2

HARDWARE ABBREVIATIONS	
BEST	BES
HES INNOVATION	HES
PRECISION	PRE
ROCKWOOD	ROC
STANLEY	STA

**HARDWARE SETS:**  
PROVIDE BASIS OF DESIGN ITEMS BELOW, OR EQUAL, FOR FIRE RATING NOTED.

HARDWARE SET 1 (TYPICAL DOOR, ACCESS CONTROL, 90 MIN)					
3	HINGES	FBB191	4.5" x 4.5"	630	STA
1	MORTISE EXIT	FL2308 x M4908A	36"	630	PRE
1	MORTISE CYLINDER	1E 74		626	BES
1	ELECTRIC STRIKE	8000		630	HES
1	CLOSER	QDC115		689	STA
1	KICKPLATE	K1050	10" x 34"	630	ROC
1 SET	SMOKESEAL	S88BL	17"		PEM

\* CARD READER BY ACCESS CONTROL